


[Return to Previous Page](#)

Help for this report: This report contains most of the data from the facility record including inspections, MITs, permit information and project status. You can select/copy and "paste special- unformatted text" all or part of this page to a text document to start correspondence about the facility.

Facility

Lucky Eagle Casino
12888 188th Ave SW
Rochester, WA 98579

GIS: 46.81179, -123.14975
Local Identifier: none
UIC Facility ID: WA105T5-12-90222
Tribal Land: Chehalis
Ownership:

Contacts

Contact Type: Other
Glen Connelly
Chehalis Tribe Natural Resources Department
Chehalis Tribe Natural Resources Dept
Oakville, WA 98568
email: gconnelly@chehalis tribe.org
Contact Type: Operator
Jeff Young
Lucky Eagle Casino
12888 188th Ave SW
Rochester, WA 98579
email: jeff.young@luckyeagle.com

Well Summary

6 - Active - 5W12 Wastewater Treatment Plant Effluent Injection - as of 04/14/2011

Named Wells

| Well Name | Operating Status | Status Date | R10 Well Type Name | Well Type Date |
|----------------------------|------------------|--------------|--|----------------|
| Drip Field Zone 6 - Active | | - 04/14/2011 | - 5W12 Wastewater Treatment Plant Effluent Injection - | 04/29/2011 |
| Drip Field Zone 5 - Active | | - 04/14/2011 | - 5W12 Wastewater Treatment Plant Effluent Injection - | 04/29/2011 |
| Drip Field Zone 4 - Active | | - 04/14/2011 | - 5W12 Wastewater Treatment Plant Effluent Injection - | 04/29/2011 |
| Drip Field Zone 3 - Active | | - 04/14/2011 | - 5W12 Wastewater Treatment Plant Effluent Injection - | 04/29/2011 |
| Drip Field Zone 2 - Active | | - 04/14/2011 | - 5W12 Wastewater Treatment Plant Effluent Injection - | 04/29/2011 |
| Drip Field Zone 1 - Active | | - 04/14/2011 | - 5W12 Wastewater Treatment Plant Effluent Injection - | 04/29/2011 |

Other Ground Water Considerations For Facility

No Non-UIC Discharges recorded.

Inspections in the last 10 Years

No inspections recorded in iWells database over the last 10 years.

Mechanical Integrity Tests

No mechanical integrity tests found.

Permit & Permit Activity

No permit or permit activity found.

Violations

No violations found.

Enforcement Actions

No enforcement actions found.

Attachments

no data found.

Project Status and Comments

| Followup Date ▼ | Status | Action Date | Last Update | Action Needed | First Mid | Last Comments | Comments Overflow | Username |
|--------------------|-------------------|----------------|----------------|------------------|--------------|--|----------------------|----------|
| - | Inventory Only | 04/14/2011 | 04/11/2013 | - | - | IHS visited site to provide UIC assistance and noted the following: Wastewater from the casino is treated at the MBR plant. The low pressure drip field is about 5 acres and 25 miles of low pressure drip line, buried about 8 inches underground. There are 6 zones, two were designated for hotel and 4 for the casino but currently wastewater from both is treated together. The drip field was installed in 2007 but as of 2011 it serves mainly as a backup disposal method. MBR effluent goes to the wetland and only is discharged to the drip field as needed or on occasion to maintain functionality of the drip field. Normal flow of wastewater is casino ww to septic tanks to MBR to wetland OR casino ww to septic tanks to MBR to lagoon cell #1 to drip field. Lagoon cell #2 can also receive MBR effluent after chlorination. Eventually cell #2 will be set up to pump reuse water back into the casino for fire flow and toilet flushing, but as of April, 2011 the plumbing for this is not in place yet. Parking lot catch basins collect stormwater and discharge to swales and the lower area East of the Casino and hotel. | - | JPARKER |

Reference Key

| Key | Facility | Added By |
|------|--------------------|----------|
| 5195 | Lucky Eagle Casino | JPARKER |